



Shared Values Award in the Area of Clean and Safe Schools



Thursday, January 25, 2024 – 4:30pm



PhotoGrid

A photograph of an emergency scene at dusk. In the foreground, a blue and yellow metal structure, possibly a playground or exercise equipment, is partially visible. A white car is parked on the street, and a black police car is nearby. A red fire truck with "PARAMEDIC" and "62" written on it is parked on the right. A person in a brown jacket and grey skirt is walking towards the fire truck. A police officer in a black uniform is standing on the sidewalk. The background shows a residential street with houses and trees.

Thursday, 1/25

4:45pm – Incident reported

4:55pm – M&O teams were called to assist with securing the site

5:15pm – Crew mobilized at the district office to gather materials and tools

5:30pm – Crew was at Gallatin and began removal and clean up of fence parts and debris

6:00pm – Facilities scheduled Wolverine Fence to walk the site next day

8:00pm – Fence line was secured and majority of debris was removed



Friday, 1/26

6:00am – grounds crew added gravel to avoid a tripping hazard

9:00 am – site walk with Wolverine to confirm scope of work and schedule for emergency repairs

9:30am – KYA scheduled to walk playground for Monday



Saturday, 1/27

8:00am – Wolverine was on site to set
fence post in footings

2:00pm – all fence post and footings installed

Sunday, 1/28

Fence panels were installed



Monday, 1/29

11:30am - Walked with KYA on
fixes to the playground

Wednesday, 1/31

2:00pm - Playground manufacturer certified
playground equipment safe for use



Wednesday, 2/14

7:00am – rubber surface repair began

Friday, 2/16

Rubberized surfaced install was completed



THANK YOU!

David Cubas, Lead Groundskeeper

Jimmy Walton, Grounds Team Lead

Jason Bomgaars, General Maintenance Shop Lead

Gabriel Rodriguez, Skilled Trades Assistant

Peter Rudeesirichot, General Maintenance

Larry Herrington, Lead Electrician





Questions